

Note:

1. The length L is customized
2. Polarity: Crossover A-B, B-A.
3. RoHS 2.0 And Reach Compliant

MATERIAL LIST:

⑦	LC Uniboot Boot White	2pcs	
⑥	Pull rod Blue	2pcs	
⑤	LC Uniboot Clip Blue	4pcs	
④	LC Uniboot Connector Blue	4pcs	
③	LC/UPC Ferrule	2pcs	
②	LC Dust Cap White	4pcs	
①	Fiber Optical Cable Duplex $\phi 2.0$ OS2 G652.D LSZH (one tube with 2 fiber), Yellow color	L	
NO.	SPECIFICATION STANDARD	QT' Y	REMARK

TYPE	Single-Mode
Insertion LOSS	$\leq 0.3\text{dB}$
Return LOSS	$\geq 50\text{dB}$
Test Wavelength	1310nm

SYNERGY 21						
CUSTOMER		ITEM NO.	See The Chart			
PRODUCT NAME	LC-LC Uniboot OS2 Switchable Patch Cords 2.0	Manufacture country	CHINA	UNIT	MM	
DRAWNBY	CHECKBY	APPOBY	DATE			
SYNERGY 21	SYNERGY 21		2018-10-26			

		NEW	2018-10-26	A
BY	CHK	REVISION RECORD MODIFICATIONS	DATE	REV.

SYNERGY 21


LC Uniboot Connector Switch Polarity Manual

— How to guide


1 Get ready to switch




2 Open buckle



3 Shell separated



4 Rotate the spare parts A & B



5 Spare parts rotate 180°



6 Shell rotate 180°



7 Push back shell



8 Assemble push-pull knob

